




## 3 Wire Hard Start Kit

# SK3W Series



*For Professionals who Prefer  
OEM-Style 3-Wire Installation*

The SUPCO SK3W Series Hard Starts provide the service professional with an OEM option when the application calls for a hard start. Combining a potential relay and start capacitor results in a True 3-Wire solution.

### 5 Versions

Part No.	H.P. Ratings	Compressor	Maximum Operating Voltage	Start Cap. (Mfd)	Start Cap. (Voltage)
<b>SK3W2</b>	1 thru. 2 HP	Standard	500 VAC	88 - 108	330 VAC
<b>SK3W3</b>	2 ½ thru. 3 ½ HP	Standard	420 VAC	189 - 227	330 VAC
<b>SK3W5</b>	4 thru. 5 HP	Standard	420 VAC	243 - 292	330 VAC
<b>SK3W4S</b>	3 thru. 4 HP	Scroll	500 VAC	189 - 227	330 VAC
<b>SK3W6S</b>	4 ½ thru. 6 HP	Scroll	420 VAC	270 - 324	330 VAC




**SEALED UNIT PARTS CO., INC.**  
PO Box 21, 2230 Landmark Place, Allenwood, NJ USA  
732-223-6644 • Fax 732-223-1617  
www.supco.com • info@supco.com

## Benefits

- Instant re-start
- Easy installation with “fast clamp-on” connection
- Models for standard and scroll compressors

## Applications

For use on any single phase air conditioning and refrigeration unit.



## Installation Instructions

- Connect white wire to start terminal on run capacitor.
- Connect red wire to run terminal on run capacitor.
- Connect black wire using “fast clampon” connector to common wire.

Note: If the “fast clamp-on” isn't suitable for the wire size, cut it and use wire nut (included) for connection.

## “Fast Clamp-On” Connection

